
User's Manual

Model 702915/702916 Current Probe

User Registration

YOKOGAWA provides registered users with useful information and services. Please allow us to serve you best by completing the user registration form accessible from our website.

<https://tmi.yokogawa.com/support/>



Contact Us

If you want to resolve a technical support issue or need to contact YOKOGAWA, please fill out the inquiry form on our website.

<https://tmi.yokogawa.com/contact/>



Thank you for purchasing the 702915/702916 Current Probe. This user's manual explains the features, operating procedures, and handling precautions of the 702915/702916 Current Probe. To ensure correct use, please read this manual thoroughly before beginning operation. After reading this manual, keep it in a safe place.

List of Manuals

The following manuals are provided for the 702915/702916.

Manual Title	Manual Number	Description
Model 702915/702916 Current Probe User's Manual	IM 702915-01EN	This manual
702915/702916 Current Probe Safety Instruction Manual	IM 702915-92Z1 IM 00C01C01-01Z1	Document for China Safety manual (European languages)

The "EN" and "Z1" in the manual numbers are the language codes.

Contact information of Yokogawa offices worldwide is provided on the following sheet.

Document Number	Description
PIM 113-01Z2	List of worldwide contacts

Notes

- The contents of this manual are subject to change without prior notice as a result of continuing improvements to the product's performance and functionality. The figures given in this manual may differ from those that actually appear on your product.
- Every effort has been made in the preparation of this manual to ensure the accuracy of its contents. However, should you have any questions or find any errors, please contact your nearest YOKOGAWA dealer.
- Copying or reproducing all or any part of the contents of this manual without the permission of YOKOGAWA is strictly prohibited.

Revisions

January 2021	1st Edition
June 2021	2nd Edition
December 2021	3rd Edition


3rd Edition: December 2021 (YMI)

All Rights Reserved, Copyright © 2021 YokogawaTest & Measurement Corporation

Checking the Package Contents

The following items are included. If the wrong items have been delivered, if items are missing, or if there is a problem with the appearance of the items, contact your nearest YOKOGAWA dealer.

- 702915 or 702916: 1 (see figure below)
- Manuals: 1 set (see List of Manuals above)
- Carrying case: 1



Safety Precautions

This instrument is designed to be used by a person with specialized knowledge.

This instrument meets the requirements of IEC-61010.

The general safety precautions described herein must be observed during all phases of operation. If the instrument is used in a manner not specified in this manual, the protection provided by the instrument may be impaired. YOKOGAWA assumes no liability for the customer's failure to comply with these requirements. In addition, before using the probe, read the manuals of the measuring instrument to thoroughly familiarize yourself with its specifications and operation.

The following symbols are used on this instrument.



Warning: handle with care. Refer to the user's manual or service manual. This symbol appears on dangerous locations on the meter which require special instructions for proper handling or use. The same symbol appears in the corresponding place in the manual to identify those instructions.



This symbol indicates that the instrument cannot be used on electric circuits that may cause an electrical shock or electrical burn.

French



Avertissement: À manipuler délicatement. Toujours se reporter aux manuels d'utilisation et d'entretien. Ce symbole a été apposé aux endroits dangereux de l'instrument pour lesquels des consignes spéciales d'utilisation ou de manipulation ont été émises. Le même symbole apparaît à l'endroit correspondant du manuel pour identifier les consignes qui s'y rapportent.



Ce symbole indique que l'instrument ne doit pas être utilisé sur des circuits électriques susceptibles de provoquer un choc électrique ou une brûlure électrique.

Notes about Usage



WARNING

- This instrument is a probe for measuring current. Use it only for measuring current.
- Do not clamp a bare conductor. Such act is dangerous because the core and shield case are not insulated.
- Be careful not to damage the insulation cover of the conductor.
- If the waveform measuring instrument has measurement terminals other than the terminal that the output terminal (BNC) of this instrument (BNC) is connected to, be careful of the following so that connecting other inputs to those terminals do not make the connected terminal of this instrument or the internal circuitry live and dangerous.
 - Be sure to ground the measurement instrument.
 - When connecting the probe to the object under measurement, be careful of electric shock. Do not remove the probe from the measurement instrument while the probe is connected to the object under measurement.
 - Before connecting the probe to the object under measurement, check that the measuring instrument and the power supply are grounded properly and that the probe output connector and power plug are connected to the measuring instrument's BNC connector and power supply receptacle, respectively.
 - Refer to the precautions (warnings) regarding electric shock and other safety matters of the devices to be connected, and use the devices carefully.
- Do not let the instrument get wet or operate it with wet hands. Doing so may cause electric shock.

- Do not block the vent holes on the side and bottom of the instrument's terminator. Doing so will cause the internal temperature to rise and may lead to fire or malfunction.
 - If you want to connect this instrument to a measuring instrument on which isolation is not available between the input terminal and case or between the input terminal and other input terminals, note the following.

The instrument's reference potential is the grounding potential. Do not apply electric potential with different grounds to the other input terminals. Doing so will cause short circuit current to flow from the ground terminal through the 701934 power supply unit or this instrument and may cause electric shock or damage to the devices.
 - Do not short-circuit between the two measurement lines with the metal part of the sensor unit. It may lead to a serious accident such as the occurrence of an arc.
 - Use this instrument within the operating temperature and humidity ranges.
 - To prevent electric shock or fire or damage to this instrument, do not install in the following places.
 - In direct sunlight or hot location.
 - In the presence of flammable gases or vapors. Using this instrument in the following environment is extremely dangerous.
 - In a dusty environment or in an environment where the instrument is exposed to water, oil, chemicals, or solvents. This instrument is not waterproof or dustproof.
 - In a strong magnetic field or near objects charged with static electricity.
 - Near a high frequency dielectric heating device, IH cookware, or other dielectric heating equipment.
 - In an environment subject to large levels of mechanical vibration.
 - Near high frequency power equipment.
-



AVERTISSEMENT

- Cet équipement est une sonde permettant de mesurer le courant. Utilisez cet équipement uniquement pour mesurer le courant.
- Ne serrez pas un conducteur nu. Une telle action est dangereuse, car le noyau et le casier de blindage ne sont pas isolés.
- Faites attention de ne pas endommager le cache d'isolation du conducteur.
- Si l'équipement de mesure de l'onde de forme est doté de bornes de mesure autres que la borne à laquelle la borne de sortie (BNC) de cet équipement (BNC) est reliée, soyez attentif à ce qui suit, de manière à ce que le fait de raccorder d'autres entrées à ces bornes n'active pas la borne raccordée de cet équipement ou les courts-circuits internes, ce qui pourrait être dangereux.
 - Assurez-vous de relier à la terre l'équipement de mesure.
 - Lorsque vous raccordez la sonde à l'objet à mesurer, soyez attentif au choc électrique. Ne retirez pas la sonde de l'équipement de mesure si elle est raccordées à l'objet à mesurer.
 - Avant de raccorder la sonde à l'objet à mesurer, vérifiez que l'équipement de mesure et l'alimentation électrique sont correctement reliés à la terre et que le connecteur de sortie de la sonde et la fiche secteur sont respectivement raccordés au connecteur BNC de l'équipement de mesure et à la prise secteur.
 - Reportez-vous aux mises en garde (avertissements) concernant le choc électrique et d'autres points de sécurité des appareils à raccorder et utilisez les appareils avec précaution.
- Évitez que l'équipement ne soit mouillé et ne le manipulez pas avec des mains humides. Ceci risquerait d'entraîner un choc électrique.
- N'obstruez pas les orifices de ventilation situés sur le côté et en bas du terminateur de l'équipement. Cela risquerait sinon de faire augmenter la température interne et d'entraîner un incendie ou un dysfonctionnement.

- Si vous souhaitez raccorder cet équipement à un équipement de mesure sur lequel il n'y a pas d'isolation entre la borne d'entrée et le casier ou entre la borne d'entrée et les autres bornes d'entrée, veuillez noter ce qui suit. Le potentiel de référence de l'équipement est le potentiel de mise à la terre. N'appliquez pas de potentiel électrique avec différentes terres à d'autres bornes d'entrée. Cela risquerait d'entraîner la circulation d'un courant de court circuit sortant de la borne de terre à travers l'alimentation électrique 701934 ou à travers cet équipement et cela risquerait d'entraîner un choc électrique ou d'endommager les appareils.
 - Ne pas court-circuiter entre les deux lignes de mesure avec la partie métallique du capteur. Cela peut entraîner un accident grave tel que l'apparition d'un arc.
 - Utilisez cet équipement dans les plages de température de fonctionnement et d'humidité.
 - Pour éviter tout choc électrique ou tout incendie ou encore éviter d'endommager cet équipement, ne l'installez pas dans les endroits suivants.
 - Exposé aux rayons directs du soleil ou dans un endroit chaud.
 - Au contact de gaz ou de vapeurs inflammables. Il est extrêmement dangereux d'utiliser cet équipement dans l'environnement suivant.
 - Dans un environnement poussiéreux ou dans un environnement où l'instrument est exposé à l'eau, à l'huile, aux produits chimiques ou aux solvants. Cet instrument n'est pas étanche à l'eau ni à la poussière.
 - Dans un champ magnétique puissant ou à proximité d'objets chargés d'électricité statique.
 - À proximité d'un radiateur diélectrique à haute fréquence, d'articles culinaires IH ou d'un équipement de chauffage diélectrique
 - Dans un environnement soumis à des niveaux élevés de vibrations mécaniques
 - À proximité d'un équipement électrique à haute fréquence"
-




CAUTION

- Avoid vibration and shock during shipping and handling. Take extra care not to drop the probe.
- Avoid storing or using the probe in direct sunlight or in areas with high temperature, humidity, or condensation. Deformation and insulation deterioration can occur causing the probe to no longer meet the specifications.
- Before use, inspect and check the operation of the probe to verify that it has not been damaged as a result of storage, transportation, and other conditions. If damage is detected, contact your nearest YOKOGAWA dealer.
- The sensor head is an intricately assembled component made of a molded part, ferrite core, Hall effect element, and so on. It can be damaged due to drastic changes in ambient temperature, mechanical stress, or shock. Handle it with care.
- The facing surfaces of the sensor head are precisely ground. Handle with care because if the surfaces are scratched, the performance will be affected.
- If dirt or the like adheres to the facing surfaces of the sensor head, wipe them with a soft cloth or the like. Dirty surfaces may affect the performance.
- To prevent broken cables, do not pull on the sensor cables or power cables.
- Static electricity can damage the current sensor. Be careful not to apply static electricity to current sensors. Below are some examples.
 - Do not touch the sensor head with an object charged with static electricity.
 - Do not touch the sensor head with an object whose electric potential is different.

- Do not touch the core surface with static electricity charged body parts when cleaning the facing surfaces of the sensor head.
(When cleaning the surfaces, take static electricity measures such as wearing an antistatic wrist strap.)
- To wipe off dirt from the instrument, apply a small amount of water or neutral agent to a soft cloth and wipe gently. Never use agents containing benzene, alcohol, acetone, ether, ketone, thinner, or gasoline. Doing so may deform or discolor the instrument.
- Do not apply strong shock or force to the terminator when the probe is connected to the measuring instrument. Doing so may damage the probe or the measuring instrument.
- Do not place the instrument on an unstable or sloped surface. The instrument may fall or roll and cause injury or damage to the instrument.
- Do not turn the terminator of this instrument when it is connected to the waveform measuring instrument. Doing so can damage the terminator or the input terminal of the waveform measuring instrument.
- Do not allow current to flow through the instrument when the connected waveform measuring instrument is turned off. Doing so can damage the instrument or the waveform measuring instrument.
- When connecting or disconnecting this instrument from the waveform measuring instrument, align the terminator straight with the waveform measuring instrument's terminal to prevent damaging the terminator.
- To prevent damaging this instrument's output terminal when you remove this instrument from the waveform measuring instrument, pull the lock release lever completely toward you, and then remove it.

Safety Precautions

- Do not bring conductors running 10 kHz or higher current near the instrument's sensor head. The sensor head temperature may increase due to self-heating from the current running through the conductor and may be damaged. As shown in the figure below, if one of bidirectional conductors is clamped and the other conductor is near the sensor head, the self-heating induced by the bidirectional current, even if the current is less than the maximum rated current, will cause a large temperature increase. Be careful as this may damage the sensor head.



- Even when the current is less than the maximum rated current, self-heating may damage the instrument. The maximum rated current is a recommended value when a sine signal is applied under standard conditions. Self-heating increases if the ambient temperature increases or if the measured current waveform contains other frequency components. See the derating characteristics in the product specifications.
- In addition to the maximum rated current, the product specifications that indicate the maximum input range include “maximum peak current (discontinuous),” which is an absolute upper limit that cannot be exceeded even for an instant. To prevent damaging the instrument, do not measure current that exceeds the maximum peak current.
- The overload warning may not work when current outside the overload detection frequency range is measured. Regardless of whether the OVERLOAD LED is blinking, be careful not to exceed the maximum rated current.

- Lock the jaws except when clamping to the conductor to be measured and when removing it from the conductor. Leaving it open can damage the product.
 - If the resonant sound increases during use, the spacing between the upper and lower sensors may be have widened. The sensor characteristics may change, so we recommend calibrating the sensor.
 - To prevent vent holes from clogging, clean them regularly. Clogged vent holes will reduce the cooling effect inside the instrument and may cause it to break.
-

French




ATTENTION

- Évitez les vibrations et les chocs au cours de l'expédition et de la manipulation. Faites particulièrement attention à ne pas faire tomber la sonde.
- Évitez de stocker ou d'utiliser la sonde en l'exposant aux rayons directs du soleil ou dans des zones à haute température, forte humidité ou forte condensation. Une déformation et une détérioration de l'isolation peuvent se produire et avoir pour conséquences que la sonde ne soit plus conforme aux spécifications.
- Avant l'utilisation, inspectez et contrôlez le fonctionnement de la sonde afin de vérifier qu'elle n'a pas été endommagée à cause du stockage, du transport et d'autres opérations. Si un endommagement est détecté, contactez votre distributeur YOKOGAWA le plus proche.
- La tête du capteur est un composant assemblé de manière complexe et composé d'une pièce moulée, d'un noyau de ferrite, d'un élément d'effet Hall etc. Ce composant risque de s'endommager suite à des changements brusques de température ambiante, à une contrainte mécanique ou un choc. Manipulez-le avec soin.
- Les faces de la tête du capteur sont mises à la terre avec précision. Manipulez-les avec soin, car si elles sont rayées, leurs performances seront altérées.

Safety Precautions

- Si de la poussière ou autre vient se coller sur les faces de la tête du capteur, essuyez-les avec un chiffon doux ou quelque chose de similaire. Des surfaces poussiéreuses peuvent altérer les performances.
- Afin d'empêcher les câbles de casser, ne tirez pas sur les câbles du capteur ou d'alimentation.
- L'électricité statique risque d'endommager le capteur de courant. Faites attention de ne pas appliquer d'électricité statique sur les capteurs de courant. Voici ci-dessous quelques exemples.
 - Ne touchez pas la tête du capteur avec un objet chargé d'électricité statique.
 - Ne touchez pas la tête du capteur avec un objet au potentiel électrique différent.
 - Ne touchez pas la surface du noyau avec des parties du corps chargées d'électricité statique lorsque vous nettoyez les faces de la tête du capteur.
(Lorsque vous nettoyez les surfaces, prenez des mesures anti-électricité statique telles que le port d'un bracelet antistatique.)
- Pour dépoussiérer au chiffon l'équipement, appliquez une petite quantité d'eau ou d'agent neutre sur un chiffon doux et essuyez soigneusement. N'utilisez jamais d'agent contenant du benzène, de l'alcool, de l'acétone, de l'éther, de la cétone, du diluant ou de l'essence. Cette action risque de déformer ou de décolorer l'équipement.
- N'appliquez pas de choc puissant ou n'exercez pas de force sur le terminateur lorsque la sonde est raccordée à l'équipement de mesure. Cela pourrait endommager la sonde ou l'équipement de mesure.
- Ne placez pas l'équipement sur une surface instable ou inclinée. L'équipement risquerait de tomber ou de rouler et d'entraîner des blessures ou encore de s'endommager.
- Ne faites pas pivoter le terminateur de cet équipement lorsqu'il est raccordé à l'équipement de mesure de la forme d'onde. Ceci risquerait d'endommager le terminateur ou la borne d'entrée de l'équipement de mesure de la forme d'onde.

- Ne laissez pas le courant circuler à travers l'équipement lorsque l'équipement de mesure de la forme d'onde raccordé est éteint. Cela pourrait endommager l'équipement ou l'équipement de mesure de la forme d'onde.
- Lors du branchement ou du débranchement de cet équipement de l'équipement de mesure de la forme d'onde, alignez le terminateur avec celui de l'équipement de mesure de la forme d'onde afin d'éviter d'endommager le terminateur.
- Afin d'éviter d'endommager la borne de sortie de cet équipement lorsque vous retirez cet équipement de l'équipement de mesure de la forme d'onde, tirez complètement vers vous le levier de déverrouillage, puis retirez-le.
- N'appliquez pas un courant de 10 kHz ou plus sur les conducteurs à proximité de la tête de capteur de l'équipement. La température de la tête du capteur risque d'augmenter suite à une surchauffe automatique due au courant circulant à travers le conducteur, ce qui risque d'entraîner un endommagement. Comme l'indique la figure ci-dessous, si l'un des conducteurs bidirectionnels est serré et que l'autre conducteur se trouve à proximité de la tête du capteur, la surchauffe automatique due au courant bidirectionnel, même si l'intensité est inférieure à l'intensité nominale maximale, risque d'entraîner une importante augmentation de la température. Opérez avec précaution, ceci risque d'endommager la tête du capteur.



- Même si l'intensité du courant est inférieure à l'intensité nominale maximale, la surchauffe automatique risque d'endommager l'équipement.

Safety Precautions

L'intensité nominale maximale est une valeur conseillée lorsqu'un signal sinusoïdal est appliqué dans les conditions standards. La surchauffe automatique augmente si la température ambiante augmente ou si la forme d'onde d'intensité mesurée contient d'autres composants de fréquence. Reportez-vous aux caractéristiques de déclassement figurant dans les spécifications du produit.

- En plus de l'intensité nominale maximale, les spécifications du produit indiquant la plage d'entrée maximale comprennent le « pic d'intensité maximale (en discontinu) », qui correspond à une limite supérieure absolue qui ne peut être dépassée même un instant. Afin d'éviter que l'équipement ne s'endommage, ne mesurez pas l'intensité qui dépasse l'intensité de pic maximale.
- L'avertissement en cas de surcharge risque de ne pas fonctionner lors de la mesure du courant en dehors de la plage de fréquence de détection de surcharge. Que la LED de SURCHARGE clignote ou non, faites attention de ne pas dépasser le courant nominal maximal.
- Verrouiller les mâchoires sauf lors du serrage sur le conducteur à mesurer et lors de son retrait du conducteur. Le laisser ouvert peut endommager le produit.
- Si le son résonnant augmente pendant l'utilisation, cela signifie que l'espace entre les capteurs supérieur et inférieur a peut-être été augmenté. Les caractéristiques du capteur peuvent changer, donc nous vous conseillons de calibrer le capteur.
- Afin d'éviter d'obstruer les orifices de ventilation, nettoyez-les régulièrement. Les orifices de ventilation obstrués réduisent l'effet de refroidissement à l'intérieur de l'équipement et risquent de le casser.

Note

- Accurate measurements may not be possible near objects with strong electromagnetic fields such as transformers, large current circuits, and wireless equipment.
 - Depending on the current frequency that is measured, oscillation may occur, but this has no effect on measurements.
-

Regulations and Sales in Various Countries and Regions

Waste Electrical and Electronic Equipment (WEEE)



(EU WEEE Directive valid only in the EEA* and UK WEEE Regulation in the UK)

This product complies with the WEEE marking requirement. This marking indicates that you must not discard this electrical/electronic product in domestic household waste. When disposing of products in the EEA or UK, contact your local Yokogawa office in the EEA or UK respectively.

* EEA: European Economic Area

Authorized Representative in the EEA (AR)

Yokogawa Europe B. V. is the authorized representative of Yokogawa Test & Measurement Corporation for this product in the EEA. To contact Yokogawa Europe B. V., see the separate list of worldwide contacts, PIM 113-01Z2.

Disposal

When disposing of YOKOGAWA products, follow the laws and ordinances of the country or region where the product will be disposed of.

Conventions Used in This Manual



Improper handling or use can lead to injury to the user or damage to the instrument. This symbol appears on the instrument to indicate that the user must refer to the user's manual for special instructions. The same symbol appears in the corresponding place in the user's manual to identify those instructions. In the user's manual, the symbol is used in conjunction with the word "WARNING" or "CAUTION."

WARNING

Calls attention to actions or conditions that could cause serious or fatal injury to the user, and precautions that can be taken to prevent such occurrences.

CAUTION

Calls attention to actions or conditions that could cause light injury to the user or damage to the instrument or user's data, and precautions that can be taken to prevent such occurrences.

Note

Calls attention to information that is important for the proper operation of the instrument.

French

AVERTISSEMENT

Attire l'attention sur des gestes ou des conditions susceptibles de provoquer des blessures graves (voire mortelles), et sur les précautions de sécurité pouvant prévenir de tels accidents.

ATTENTION

Attire l'attention sur des gestes ou des conditions susceptibles de provoquer des blessures légères ou d'endommager l'instrument ou les données de l'utilisateur, et sur les précautions de sécurité susceptibles de prévenir de tels accidents.

Contents

List of Manuals	1
Checking the Package Contents	2
Safety Precautions	3
The following symbols are used on this instrument	3
Notes about Usage	4
Regulations and Sales in Various Countries and Regions	15
Conventions Used in This Manual	16
1. Product Overview	18
2. Configuration and Functions	19
Configuration and Component Names	19
Component Functions	20
LED Display Functions	22
3. Operation Procedure	23
Handling Precautions	23
Measurement Preparation	24
Demagnetization and Zero Adjustment	27
Measurement Method	30
Ending Measurement	35
4. Product Specifications	37
Electrical Specifications	37
General Specifications	38
Compliant Standards	39
External Dimensions	39
5. Typical Characteristics	40
6. Troubleshooting	46
Before Sending the Instrument for Repair	46
Types of Errors and Corrective Actions	47

1. Product Overview

Model 702915 and Model 702916 Current Probes are clamp-on current probes that feature high current-detection sensitivity and broad frequency band. Both probes use three (3) current ranges to detect a variety of current waveforms from 1 mA to 30 Arms with a single unit.


The probes can be connected directly through the termination unit to a BNC input terminal of a waveform measuring instrument such as a Yokogawa's oscilloscope and recorder and then current waveforms are easily measured and observed simply by clamping the target conductor.

Model 702915 covers frequency range from DC to 50 MHz.

Model 702916 covers frequency range from DC to 120 MHz.

2. Configuration and Functions

Configuration and Component Names



Component Functions

Sensor head

Inside the tip of the sensor unit, sensor head detects the current in a conductor. It is an intricately assembled component made of a molded part, ferrite core, Hall effect element, and so on. It needs to be handled with care as it can be damaged from drastic ambient temperature changes, mechanical stress or shock, and so on.

Jaw

Clamp this part around a conductor to be measured by operating the opening lever, which allows the upper jaw to slide.

Opening lever

This lever is for opening and closing the upper jaw. By retracting the upper jaw with this lever, it can be locked in place.

Sensor aperture

A conductor to be measured must pass through this aperture. Insulated conductor can be measured. Measurable diameter of conductors is 5 mm or less.

Current direction mark

Clamp the jaw around a conductor so this mark matches the current direction of the conductor to be measured.

Lock release lever

This lever is for releasing the output terminal lock. To remove the output terminal, release the lock with this lever first.

DEMAG/AUTO ZERO key

Press and hold (about 1 second) to perform demagnetization and zero adjustment.

Short press (less than 0.5 seconds) to perform only zero adjustment. The demagnetization function cancels the magnetization of the magnetic core caused by power ON/OFF or excessive input. The auto-zero function corrects unnecessary effects such as offset voltage and temperature drift of the instrument. Following demagnetization, it is automatically zero-adjusted.

Range key

Each time pressing range up/down keys, the current range switches. Choose from three current ranges: 0.5 A, 5 A, 30 A. The indicator for the selected range lights up.

Output terminal

This terminal outputs measured current waveforms at a certain rate. Connect it to the BNC input terminal of an oscilloscope. Depending on the current range selected, the output rate varies between 10 V/A (0.5 A range), 1 V/A (5 A range), and 0.1 V/A (30 A range).

Power plug

This plug is connected to a power terminal of an oscilloscope with probe power supply or to a power supply receptacle of a power supply unit (model 701934, sold separately) in order to supply power to 702915/702916.

Overload

When a current (DC and 45 to 66 Hz sine wave) exceeding the following level specified for each current range is detected, the overload indicator blinks rapidly.

30 A range: 32.5 ± 2.5 Arms

5 A range: 5.25 ± 0.25 Arms

0.5 A range: 0.525 ± 0.025 Arms

The sampling frequency for overload detection is 7.8125 kHz (typical), and the checking cycle is 500 ms (typical).

LED Display Functions

For details on each error, see "Types of Errors and Corrective Actions."
LEDs other than POWER light up for about 1 second at startup, but this is normal.

POWER (green)

Solid	Power supplied to the product.
Blinks rapidly	Checksum error occurred.

OVERLOAD (red)

Blinks 3 times	Demag/auto-zero error occurred.
Blinks rapidly	An overload detected. Switched to protection mode. Checksum error occurred.

JAW UNLOCKED (red)

Solid	The upper jaw not locked.
Blinks 3 times	Demag/auto-zero error occurred.
Blinks rapidly	Switched to protection mode. Checksum error occurred.

DEMAG/AUTO ZERO (orange)

Blinks slowly	Demag/auto-zero not performed.
Solid	Demag/auto-zero in progress.
Off	Demag/auto-zero performed.
Blinks 3 times	Demag/auto-zero error occurred.
Blinks rapidly	Switched to protection mode. Checksum error occurred.

RANGE (green)

Solid	Indicates the set current range.
Blinks rapidly	Switched to protection mode. Checksum error occurred.

3. Operation Procedure

Handling Precautions



WARNING

- Do not clamp a bare conductor. Such act is dangerous because the core and shield case are not insulated.
- Be careful not to damage the insulation cover of the conductor.
- Do not short-circuit between the two measurement lines with the metal part of the sensor unit. It may lead to a serious accident such as the occurrence of an arc.

French



AVERTISSEMENT

- Ne serrez pas un conducteur nu. Une telle action est dangereuse, car le noyau et le casier de blindage ne sont pas isolés.
- Faites attention de ne pas endommager le cache d'isolation du conducteur.
- Ne pas court-circuiter entre les deux lignes de mesure avec la partie métallique du capteur. Cela peut entraîner un accident grave tel que l'apparition d'un arc.

Measurement Preparation



CAUTION

- When connecting the probe to a waveform measuring instrument, attach or detach it straight to the BNC terminal of the waveform measuring instrument so that the termination part of the probe may not be damaged.
- When using a 702915/702916 current probe, it may not be possible to use multiple active probes at the same time with the 701934 power supply, or the probe power supply from a YOKOGAWA waveform measuring instrument. Make sure that the total current consumption of each active probe does not exceed the current specifications of the probe power supply. The current consumption of the probe depends on the measured current.

See the following YOKOGAWA website for the usage limitations for each measuring instrument.

<https://tmi.yokogawa.com/solutions/products/oscilloscopes/current-probes/>

French



ATTENTION

- Lorsque vous connectez cet instrument à un instrument de mesure de forme d'onde, fixez-le ou détachez-le directement à la borne BNC de l'instrument de mesure de forme d'onde afin que la partie terminale de cet instrument ne puisse pas être endommagée.

- Si une sonde de courant 702915/702916 est utilisée, suivant l'intensité mesurée, vous risquez de ne pas pouvoir utiliser plusieurs sondes actives avec l'alimentation de la sonde 7001934 ou l'alimentation de sonde d'un équipement de mesure de la forme d'onde YOKOGAWA.

La consommation de courant de la sonde de courant 702915/702916 dépend de l'intensité mesurée. Assurez-vous que la consommation totale de courant de toutes les sondes actives ne dépasse pas les spécifications de courant de l'alimentation de la sonde 701934 ou de l'alimentation de sonde d'un équipement de mesure de la forme d'onde YOKOGAWA.

Pour plus d'informations concernant les limites d'utilisation conformes à chaque équipement de mesure, reportez-vous à la page Web YOKOGAWA ci-dessous.

<https://tmi.yokogawa.com/solutions/products/oscilloscopes/current-probes/>

Prepare this instrument and a waveform measuring instrument such as a digital oscilloscope or recorder. If the waveform measuring instrument is not equipped with a probe power supply, prepare also a 701934 power supply.

- 1.** If you are using a YOKOGAWA waveform measuring instrument with a probe power supply, turn the waveform measuring instrument off. If you are using the 701934, turn it off.
- 2.** Hold down the instrument's opening lever until the JAW UNLOCKED indication disappears to lock the sensor head. Do not clamp the conductor at this point.
- 3.** Connect this instrument's power cable to a YOKOGAWA waveform measuring instrument with a probe power supply or to the power supply receptacle of a 701934 power supply. Firmly connect so that the power cable shell locks in place.

3. Operation Procedure

4. Turn on the waveform measuring instrument with a probe power supply or the 701934 power supply. The instrument's power lamp (POWER) illuminates, and the DEMAG/AUTO ZERO LED blinks slowly while demagnetization and zero adjustment are taking place.

Note

- The instrument's output is internally terminated. Use a waveform measuring instrument with an input impedance of 1 M Ω or higher. Correct measurement is not possible with an input impedance of 50 Ω .
 - The offset drift may be large immediately after starting to supply power due to instrument's self-heating and other effects. To make accurate measurements, warm up for at least 30 minutes.
-

Demagnetization and Zero Adjustment



WARNING

While a conductor is clamped, do not hold down the DEMAG/AUTO ZERO switch to demagnetize. Doing so can damage the circuit under measurement or cause electric shock or burns.

French



AVERTISSEMENT

Si un conducteur est serré, ne maintenez pas enfoncé l'interrupteur DEMAG/AUTO ZERO (Démagnétisation/remise à zéro automatique) pour la démagnétisation. Cette action risquerait d'endommager le circuit à mesurer ou d'entraîner un choc électrique ou une combustion.



CAUTION

Do not demagnetize with a conductor clamped. The current that flows through the conductor as a result of demagnetization may damage components of the circuit under measurement. For the same reason, make sure that the conductor is not clamped when supplying power to the 702915/702916. A demagnetization waveform may be generated when power is supplied.

3. Operation Procedure

French



ATTENTION

N'effectuez pas de démagnétisation avec un conducteur serré. Le courant qui circule à travers le conducteur suite à une démagnétisation risque d'endommager les composants du circuit à mesurer. Pour la même raison, assurez-vous que le conducteur n'est pas serré lors de l'alimentation en courant de 702915/702916. Une forme d'onde de démagnétisation peut être générée lors d'une alimentation en courant.

Be sure to perform demagnetization and zero adjustment before making measurements. Demagnetization is used to eliminate the magnetic charge of the magnetic core that occurs from turning the power on and off, excessive input, and so on. Zero adjustment is used to correct the instrument's inherent offset voltage and offset voltage variation caused by temperature changes or the like.

1. Set the input coupling of the waveform measuring instrument to GND, and adjust the zero position on the display.
2. Set the input coupling of the waveform measuring instrument to DC.
3. Connect this instrument's output terminal to the BNC input terminal of the waveform measuring instrument. Insert it straight until it clicks in place to securely lock it.

Connection is possible regardless of whether the lock pin of the waveform measuring instrument's BNC input terminal is arranged horizontally or vertically.

4. Hold down **DEMAG/AUTO ZERO** for about 1 second. Be careful not to press too hard. Demagnetization is performed followed by zero adjustment.

While demagnetization and zero adjustment are taking place, the DEMAG/AUTO ZERO LED is lit. When demagnetization and zero adjustment is complete, the LED turns off.

If the DEMAG/AUTO ZERO LED does not turn off but blinks even if you press the DEMAG/AUTO ZERO switch, this indicates that demagnetization and zero adjustment have not been completed normally. See “Types of Errors and Corrective Actions” for details.

Note

- When connecting the probe to a non-BNC input terminal through a BNC-to-banana adapter or the like, pay attention to the polarity of the input terminal.
 - Resonant sound may occur when you perform demagnetization, but this has no effect on measurements.
 - After starting to supply power or after a condition in which the rating is exceeded is removed, the DEMAG/AUTO ZERO LED blinks slowly until demagnetization and zero adjustment are executed.
 - While demagnetization is taking place (the DEMAG/AUTO ZERO LED is on), a demagnetization waveform (waveform that attenuates over time) is output from this instrument's output terminal and appears on the waveform measuring instrument. The positive and negative sides of this waveform may be asymmetric, but this is not a malfunction.
 - To abort demagnetization and zero adjustment, release the sensor head lock. Then, execute demagnetization and zero adjustment again according to the procedure.
-

To Perform Only Zero Adjustment

To perform only zero adjustment (without demagnetization), press **DEMAG/AUTO ZERO** for a short time in step 4 on the previous page. The DEMAG/AUTO ZERO LED turns on. When zero adjustment is complete, the LED turns off.


Measurement Method



CAUTION

- The continuous maximum input range is a value defined based on the temperature increase due to self-heating during measurement. Do not apply current outside this range. Doing so can damage the instrument.
- The continuous maximum input range varies depending on the frequency of the measured current. See the product specifications.
- If current exceeding the continuous maximum input range is applied, the internal protection function will be activated as a result of the heat generated by the sensor, and the probe will not output correct values. If this happens, immediately remove the input (remove the sensor head from the conductor or reduce the input current to zero). Adequate cooling period will be required until the probe can output correct values again.
- In a high temperature environment, the internal overcurrent protection circuit may be activated even at currents within the continuous maximum input range.
- If current exceeding the continuous maximum input range is applied continuously or if the protection function is activated frequently, the instrument may break.
- In addition to the continuous maximum input range, the product specifications that indicate maximum input range include “discontinuous maximum peak current.” This signifies that the upper limit of waveform response is maximum peak current. Use the probe in a way that the rms value does not exceed the continuous maximum input range.
- Be sure to use the opening lever to open the upper jaw. Pressing the top core when the upper jaw is locked will damage the clamping mechanism.

- Do not apply force to the sensor head in the direction shown in the following figure.



French




ATTENTION

- La plage d'entrée continue maximale est une valeur définie en fonction de l'augmentation de température due à la surchauffe automatique au cours de la mesure. N'appliquez pas de courant en dehors de cette plage. Le cas échéant, un endommagement de l'équipement risquerait de se produire.
- La plage d'entrée continue maximale varie en fonction de la fréquence de l'intensité mesurée. Reportez-vous aux spécifications du produit.
- Si un courant dépassant la plage d'entrée continue maximale est appliqué, la fonction de protection interne est activée suite à la chaleur générée par le capteur et la sonde ne donne pas de valeur correcte. Le cas échéant, retirez immédiatement l'entrée (retirez la tête du capteur du conducteur ou remettez le courant d'entrée à zéro). La période de refroidissement adéquate sera requise jusqu'à ce que la sonde puisse donner à nouveau des valeurs correctes.
- Dans un environnement de température élevée, le circuit de protection contre la surintensité interne peut être activé même à des intensités comprises dans la plage d'entrée continue maximale.
- Si un courant dépassant la plage d'entrée continue maximale est appliqué en continu ou si la fonction de protection est régulièrement activée, l'équipement risque de se casser.


3. Operation Procedure

- En plus de la plage d'entrée continue maximale, les spécifications du produit indiquant la plage d'entrée maximale comprennent le « pic d'intensité maximale discontinue ». Cela signifie que la limite supérieure de la réponse de forme d'onde est le courant de crête maximum. Utilisez la sonde de manière à ce que la valeur rms ne dépasse pas la plage d'entrée continue maximale.
- Assurez-vous d'utiliser le levier d'ouverture pour ouvrir la tête du capteur. Le fait d'appuyer sur le noyau supérieur lorsque la tête du capteur est verrouillée endommage le mécanisme de serrage.
- N'exercez pas de force sur la tête du capteur dans le sens indiqué sur la figure ci-dessous.



Before measuring, check that there are no problems with the instrument or the measurement target and that measurement preparations have been taken.

1. Pull the sensor opening lever to open the upper jaw.
2. Align the direction of the arrow of the current direction mark indicated at the sensor tip to the direction of the measured current, and clamp so that the conductor is at the center of the sensor aperture.



3. Hold down the sensor opening lever until the JAW UNLOCKED indication disappears to lock the upper jaw. The JAW UNLOCKED LED turns off.

4. Check the LED status of Junction box. It is normal if the POWER LED and one of the RANGE LEDs are lit.
5. Press the range up/down keys of the junction box to select the current range (0.5 A, 5 A, or 30 A).
6. The current waveform can be observed on the waveform measuring instrument. The output voltage rate of the 702915 and 702916 is 10 V/A (0.5 A range), 1 V/A (5 A range), or 0.1 V/A (30 A range), depending on the current range selected. Convert the voltage sensitivity of the waveform measuring instrument to current sensitivity.

To Measure with High Accuracy

Offset voltage fluctuations of about 1 mV may occur when opening and closing the jaws. If you want to measure with high accuracy, follow the procedure below. At this time, if a large impact is applied to the sensor head, the offset voltage fluctuation may increase, so operate the lever slowly.


1. Press and hold **DEMAG/AUTO ZERO** for about 1 second.
Demagnetization and zero adjustment are performed.
2. Wait about 5 minutes for the offset drift to stabilize.
3. Use the opening lever to open and close 4 or 5 times.
4. Clamp the conductor to be measured.
5. Short press **DEMAG/AUTO ZERO** to perform only zero adjustment (not press and hold).
6. Measure the current.

Note


- The offset drift may be large immediately after starting to supply power due to instrument's self-heating and other effects, but it will stabilize for the most part in about 30 minutes.
- The offset voltage will drift due to the ambient temperature or the like, so careful attention is required when performing continuous measurement.

3. Operation Procedure

- Offset drift may increase depending on the condition of the facing surfaces. It can be improved by finishing the measurement once, removing it from the conductor to be measured, and performing demagnetization and zero adjustment again.
- On rare occasions, connecting the power plug to the power supply that is turned on may cause oscillation, but this is not a malfunction. If this occurs, you can open and close the sensor head with the opening lever to stop the oscillation and restore normal operation.
- Depending on the current frequency that is measured, resonant sound may occur, but this has no effect on measurements.
- In the high frequency region, the probe may be affected by common-mode noise by clamping the high potential side of an electric circuit. If necessary, limit the bandwidth of the waveform measuring instrument, or clamp the low potential side.



- Accurate measurements may not be possible near objects with strong electromagnetic fields such as transformers, large current circuits, and wireless equipment.
- When measuring DC or low-frequency, low current, winding the conductor several times will increase the relative sensitivity. If the conductor is wound 10 times, the probe will output 10 times the measured current. However, wind the conductor radially at a diameter of at least 20 cm.



- The measured value may be affected by the conductor position within the sensor aperture. Position the conductor at the center of the sensor window, and make the straight portion as long as possible. Avoid positioning the conductor so that it is wound locally around the sensor head.
 - To make accurate measurement, hold down the opening lever until the JAW UNLOCKED indicator disappears to ensure that the sensor head is securely closed and locked.
 - Conductor clamping and cable positioning may cause load fluctuations, affecting the observed waveform.
 - To prevent offset voltage variation from occurring, make sure that force is not applied to the jaw or opening lever during measurement.
-

Ending Measurement

Notes on Ending Measurement

To remove the instrument's power cable from the power supply, pull the power cable shell.



CAUTION

- To prevent breaking the cable, do not pull the cord when removing the output terminal from the waveform measuring instrument. Be sure remove by holding the terminator and pulling the lock release lever toward you.
 - To prevent breaking the instrument's power cable, probe power supply terminal of the waveform measuring instrument, and the power supply receptacle of the 701934 power supply unit, observe the following when removing the power cable.
 - Hold the power plug shell and remove.
 - Do not pull the cable or rotate the power plug. (Pulling the power plug shell releases the lock allowing you to remove it from the power supply receptacle.)
-

3. Operation Procedure


French



ATTENTION

- Afin d'éviter de casser le câble, ne tirez pas sur le cordon lorsque vous retirez la borne de sortie de l'équipement de mesure de la forme d'onde. Assurez-vous que vous retirez le dispositif en maintenant le terminateur et en tirant vers vous le levier de déverrouillage.
 - Afin d'éviter de casser le câble d'alimentation de l'équipement, la borne d'alimentation de la sonde de l'équipement de mesure de la forme d'onde et la prise de secteur de l'alimentation 701934, respectez les consignes ci-dessous lorsque vous retirez le câble d'alimentation.
 - Tenez le boîtier de la fiche secteur et retirez le dispositif.
 - Ne tirez pas sur le câble et ne faites pas pivoter la fiche secteur. (Le fait de tirer sur le boîtier de la fiche secteur entraîne un déverrouillage qui vous permet de le retirer de la prise secteur.)
-

1. Pull the opening lever toward you, and remove the instrument from the conductor.
2. Remove the terminator from the waveform measuring instrument. Pull the lock release lever toward you, and pull the terminator straight out.



3. Turn off the waveform measuring instrument with a probe power supply or the 701934 power supply.
4. Remove the instrument's power plug.
Hold the power plug shell and remove.
Do not pull the cable or rotate the power plug.

4. Product Specifications

Electrical Specifications

Accuracy value is for 23 ± 3 °C, 30 minutes after power-on.

Item		702915	702916
Frequency band		DC to 50 MHz (-3 dB) ¹	DC to 120 MHz (-3 dB) ¹
Rise time		7.0 ns	2.9 ns
Delay time ²	30 A range	12 ns (typical) ³	
	5 A range	12 ns (typical) ³	
	0.5 A range	13 ns (typical) ³	
Current range (Output voltage rate)		30 A range (0.1 V/A)	
		5 A range (1 V/A)	
		0.5 A range (10 V/A)	
Continuous Maximum input ⁴	30 A range	30 Arms ⁵	
	5 A range	5 Arms ⁵	
	0.5 A range	0.5 Arms ⁵	
Amplitude accuracy ⁶	30 A range	$\pm 3.0\%$ of reading ± 1 mV, $\pm 1.0\%$ of reading ± 1 mV (10 Arms or less, typical) ³	
	5 A range	$\pm 3.0\%$ of reading ± 1 mV, $\pm 1.0\%$ of reading ± 1 mV (typical) ³	
	0.5 A range	$\pm 3.0\%$ of reading ± 10 mV, $\pm 1.0\%$ of reading ± 10 mV (typical) ³	
Maximum peak current	30 A range	± 50 Apeak (maximum 2 s input)	
	5 A range	± 7.5 Apeak	
	0.5 A range	± 0.75 Apeak (less than 10 MHz), ± 0.3 Apeak (10 MHz or more)	
Noise ⁷		75 μ Arms, 60 μ Arms (typical) ³	
Insertion impedance		Depend on frequency ⁸	
Temperature characteristics of sensitivity ⁹		$\pm 2.0\%$ of reading	
Effects of radiated radio- frequency electro-magnetic field		± 10 mA or less at 3 V/m	
Effects of conducted radio- frequency electro-magnetic field		± 10 mA or less at 3 V	
Effects of external magnetic field ¹⁰		20 mA or less	5 mA or less

1 Refer to "Frequency Characteristics" for frequency characteristics diagram.

2 Delay time for input signal 1ns rising waveform.

3 "Typical" values are typical or average values and are not strictly guaranteed.

4. Product Specifications

- 4 Specified by DC and sine wave. Depending on the ambient temperature or measurement conditions, the internal temperature may increase and these values may decrease.
- 5 Frequency derating is applied. See "Frequency Derating" for details.
- 6 DC and 45 Hz to 66 Hz sine waves, within the maximum peak current of each current range.
- 7 Probe only, 0.5 A range, with 20 MHz band oscilloscope.
- 8 See to "Insertion Impedance" for details.
- 9 After automatic zero adjustment in the ambient excluding $23\text{ }^{\circ}\text{C} \pm 5\text{ }^{\circ}\text{C}$, for the following currents at 50 Hz:
30 A at 30 A range, 5 A at 5 A range, or 0.5 A at 0.5 A range.
Also, the temperature characteristics of the sensitivity are added to the amplitude accuracy.
- 10 In DC and 60 Hz, 400 A/m magnetic fields.

General Specifications

Item	Common to 702915/702916
Dimensions	Sensor unit: Approx. 155 W x 18 H x 26 D mm Junction box: Approx. 45 W x 120 H x 25 D mm Termination unit: Approx. 29 W x 83 H x 40 D mm (excluding BNC connector or protrusions)
Cord length	Sensor unit to junction box: Approx. 1500 mm Junction box to termination unit: Approx. 150 mm Power cord: Approx. 1000 mm
Weight	Approx. 370 g
Measurable conductors	Insulated conductors
Measurable diameter of conductors	5 mm or less in diameter
Connector type	BNC type
Power supply ¹	Rated supply voltage: DC $\pm 12\text{ V} \pm 0.5\text{ V}$ Maximum rated power: 7.8 VA (probe only, at 30 Arms continuously)
Consumption current	Depends on input current ²
Operating environment	Indoor use, altitude up to 2000 m
Operating temperature and humidity	0 °C to 40 °C, 80% RH or less (no condensation)
Storage temperature and humidity	-10 °C to +50 °C, 80% RH or less (no condensation)
Warming-up time	30 minutes or more

1 Power is supplied from the probe power terminals on Yokogawa's oscilloscope or Probe Power Supply Unit (model 701934, sold separately).


2 See "Consumption Current" in "Typical Characteristics" for details.

Compliant Standards

Item		Common to 702915/702916	
Safety standards		EN 61010-1 EN 61010-2-032 Type D Pollution degree 2 ¹	
EMC standards	Emissions	EN 61326-1 Class B EN 55011 Class B Group 1 EMC Regulatory Arrangement in Australia and New Zealand EN 55011 Class B Group 1	
		Immunity	EN 61326-1 Table 1 (Basic immunity requirement)
		Environmental standards ² EU RoHS Directive compliant	

- 1 Pollution degree applies to the degree of adhesion of a solid, liquid, or gas which deteriorates withstand voltage or surface resistivity. Pollution degree 2 applies to normal indoor atmospheres (usually with only non-conductive pollution).
- 2 For conformity to environmental regulations and/or standards other than EU, contact your local Yokogawa office (PIM 113-01Z2).


External Dimensions




5. Typical Characteristics

All of the characteristics shown in this section are typical. The values shown here are not strictly guaranteed.

Frequency Characteristics




702915 (50MHz) Frequency Response




702916 (120MHz) Frequency Response

Frequency Derating




702915 (50MHz) Frequency Derating




702916 (120MHz) Frequency Derating

5. Typical Characteristics

Insertion Impedance





702915 (50MHz) Insertion Impedance




702916 (120MHz) Insertion Impedance


Consumption Current



5. Typical Characteristics




Influence of Common-Mode Voltage




Influence of Common-mode Voltage (702915/702916)


Influence of Residual Magnetization



Influence of Residual Magnetization (0.5 A range)



Influence of Residual Magnetization (5 A range)



Influence of Residual Magnetization (30 A range)

6. Troubleshooting

- If damage is suspected, check “Before Sending the Instrument for Repair” before contacting your nearest YOKOGAWA dealer.
- If no waveform is displayed even after performing demagnetization and zero adjustment, the instrument may be damaged. Contact your nearest YOKOGAWA dealer.


Before Sending the Instrument for Repair

Symptom	Check and Corrective Action								
No waveform is displayed on the connected waveform measuring instrument.	• Perform demagnetization and zero adjustment again. • Verify that the waveform measuring instrument's input coupling is set to DC. If this does not resolve the issue, the instrument may be damaged. Have it repaired.								
A resonant sound is emitted by the sensor head.	A resonant sound may be emitted depending on the amplitude and frequency of the current being measured. It may also be emitted during demagnetization. This does not affect measurement.								
The resonant sound emitted by the sensor head has grown louder.	The spacing between the upper and lower sensors may have widened. The sensor characteristics may change, so we recommend calibrating the sensor.								
The positive and negative sides of demagnetization waveform are asymmetric.	This is not a malfunction. After demagnetization and zero adjustment, verify that the zero position of the waveform measuring instrument is at the correct position.								
Demagnetization and zero adjustment do not complete normally.	Demagnetization and automatic zero adjustment cannot be performed in the following circumstances: Perform the following corrective action, and then perform demagnetization and zero adjustment again. <table> <tr> <th>Condition</th><th>Corrective Action</th></tr> <tr> <td>The JAW UNLOCKED LED is lit.</td><td>Lock the sensor head. (Press the opening lever until the JAW UNLOCKED indicator turns off.)</td></tr> <tr> <td>The OVERLOAD LED is blinking.</td><td>Remove the instrument from the conductor being measured.</td></tr> <tr> <td>A current of 0.5 Arms or higher was detected.</td><td></td></tr> </table> If demagnetization and zero adjustment do not complete normally even when current is not being measured, the instrument is broken. Have it repaired.	Condition	Corrective Action	The JAW UNLOCKED LED is lit.	Lock the sensor head. (Press the opening lever until the JAW UNLOCKED indicator turns off.)	The OVERLOAD LED is blinking.	Remove the instrument from the conductor being measured.	A current of 0.5 Arms or higher was detected.	
Condition	Corrective Action								
The JAW UNLOCKED LED is lit.	Lock the sensor head. (Press the opening lever until the JAW UNLOCKED indicator turns off.)								
The OVERLOAD LED is blinking.	Remove the instrument from the conductor being measured.								
A current of 0.5 Arms or higher was detected.									

Types of Errors and Corrective Actions

The type of error on the instrument can be identified by the lighting status of the LEDs on the junction box. If an error occurs, follow the corrective action below. If the instrument needs to be repaired, contact your nearest YOKOGAWA dealer.

Protection Mode




This mode detects the abnormal internal temperature of the junction box and reduces power consumption. The current cannot be measured correctly in protection mode.

Set temperature: 80 °C (typical)

Hysteresis: 10 °C (typical)

Remove the sensor from the conductor to be measured and wait until the temperature of the Junction box drops. If pressing any key on the junction box, it will return to the normal state, so demag/auto-zero adjustment will be executed again. In addition, it is recommended to calibrate the instrument because the internal parts may be stressed by heat.

Overload



A current exceeding the following level specified for each current range is detected.


30 A range:	32.5 ± 2.5 Arms
5 A range:	5.25 ± 0.25 Arms
0.5 A range:	0.525 ± 0.025 Arms

(DC and 45 to 66 Hz sine waves)

If using the 30 A range, remove the sensor from the conductor to be measured. For the 0.5 A or 5 A range, switch to the larger current range.

Overload cannot be detected for currents momentarily exceeding the specified level or for high-frequency currents exceeding the specified level. Also, immediately after switching the current range, overload may not be detected correctly. The OVERLOAD LED may blink due to the influence of an external magnetic field when the jaws are open, but this is not a malfunction.

Demagnetizing / Automatic Zero-Adjustment Error



Demagnetizing and automatic zero-adjustment functions cannot be executed. Alternatively, demagnetizing or automatic zero-adjustment has not finished properly. The instrument is in one of the following status.

- The upper jaw not locked. (JAW UNLOCKED lights up.)
- An overload detected regardless of Jaw locked state. (OVERLOAD blinks rapidly.)
- A measured current exceeding the following values detected regardless of Jaw locked state.
0.50 ± 0.25 Arms (DC, 45 to 66 Hz sine waves)

Take any of the following actions, depending on the status after the LEDs blink 3 times. After that, demagnetizing and automatic zero-adjustment will be performed again.

6. Troubleshooting

LED Status after Blinking 3 Times

Upper jaw unlocked

Lights in green —	☐ POWER
Turns off —	☒ OVERLOAD
Lights in red —	☐ JAW UNLOCKED

Press the opening lever until the JAW UNLOCKED indicator disappears to lock the jaw.

Overload detected

Lights in green —	☐ POWER
Blinks rapidly in red —	☒ OVERLOAD
Lights in red or turns off —	☒ JAW UNLOCKED

Remove the sensor from the conductor to be measured. Then press the opening lever until the JAW UNLOCKED indicator disappears to lock the jaw.


Over 0.5 A detected

Lights in green —	☐ POWER
Turns off —	☒ OVERLOAD
Lights in red or turns off —	☒ JAW UNLOCKED

Remove the sensor from the conductor to be measured. Then press the opening lever until the JAW UNLOCKED indicator disappears to lock the jaw.

Checksum Error


All LEDs blink rapidly



There is something wrong with the internal CPU. Please request repair.

Malfunction

All LEDs turn off



The instrument is out of order. Please request repair.